Thursday, 11/9/2006 4:37:57 PM Date: Kim Johnston Use **Process Sheet** : WASHER **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 29396 **Estimate Number** : 11045 : D2813 P.O. Number : NA Part Number S.O. No. : 1/1/7 : D2813 REV A : 11/9/2006 **Drawing Number** This Issue : N/A Project Number Prsht Rev. : NA : MACHINED PARTS Type **Drawing Revision** First Issue : 26649 Material **Previous Run** 40 Um: Each : 11/24/2006 **Due Date** Qty: Written By Checked & Approved By JLM Comment Est Rev:B 00.11.16 Changed material EC **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** MDELRINR2000 **DELRIN ROUND BAR 2.00"** 1.0 0.6720 f(s) Comment: Qtv.: 0.0168 f(s)/Unit Total: Delrin Round Bar 2.00" (MDELRINR2000) HARDINGE CNC LATHE SMALL HARDINGE 2.0 Comment: 1-TURN AS PER FOLIO FA637 & DWG D2813, FOLIOREV: Done manually DWG REV: A___ 40 2-DEBURR AS REQUIRED 3.0 QC2 40 Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK 4.0 4/1 Comment: SECOND CHECK PACKAGING RESOURCE #1 5.0 **PACKAGING 1** Comment: PACKAGING RESOURCE #1 Identify and Stock 388

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGE	S				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	·	PAR #: Fault Category:	NCR: Yes	(No) DO	QA:	Date: <u> </u>	6/11/13

QA: N/C Closed: ____ Date: ____

NCR: WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC		Corrective Action Section B		Verification	Anneoval	Annroyal
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto
						,		
	:					,		

NOTE: Date & initial all entries

Date: ,

Thursday, 11/9/2006 4:37:58 PM

User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WASHER

Job Number: 29396

Part Number: D2813

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



(Lachilla

Dart Aerospace Ltd

W/O:		WORK ORDER CH	IANGES		-		•
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #· Fault Category:	NCP: Ves	No DO	Λ.	Date:	<u> </u>

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:	
			QA: N/C (Closed:	Date:	•

NCR:		V	VORK ORD	ER NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verification	Annroyal	Annessal
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		64. N					·	


NOTE: Date & initial all entries





	DESIGN #	DRAWN BY		DSPACE LTD ONTARIO, CANADA
)	CHECKED P	APPROVED	DRAWING NO.	REV. A SHEET 1 OF 1
	DATE		TITLE	SCALE
	00.11.03		WASHER	1:1
	Ι Δ Ι	00.11.03	NEW ISSUE	





SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE

MATERIAL: DELRIN OR TEFLON OR UHMW 0.063 THICK NO. TOLERANCES PER DART QSI 018 UNLESS OTHERWISE NOTED THIS PART CAN BE MADE EPON DOEE1 THIS PART CAN BE MADE FROM D2551

Copyright © 2000 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART AEROSPACE LTD	Work Order:	29396
· ac		
Description: Washer	Part Number:	D2813
	41	
Inspection Dwg: D2813 Rev: A	1	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

	X	First Article	罗 Prototype
--	---	---------------	-------------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
0 1.80	±.030	1.802	V,			
\$.516	t.028 001	0.521	$\overline{}$			
.063	± .olo	0.063	$\sqrt{}$			
				<u> </u>		
		•				
						-
		·				
	•				·	
		·				: :
		·				
-		1				
	*					4
				•		
		€				*

	*			
Measured by:	Audited by:	Un .	Prototype Approval:	11/
Date: 16/11/11	Date:	octual u	Date:	
			:	

Rev	Date	Change	Revised by	Approved
Α		New Issue	KJ/JLM	

